

<u>MODELS</u>	LC26P70EK	LC32P70EK	LC37P70EK	LC32BT8EK
	LC32GD8EK	LC32GD9EK	LC37GD8EK	LC37GD9EK
	LC32SD1EK	LC37SD1EK	LC42SD1EK	LC37GE1EK
	LC37XD1EK	LC42XD1EK	LC46XD1EK	LC52XD1EK
	LC37XD10EK	LC42XD10EK		

SYMPTOM Not all stations added to station table when tuning.

CAUSE Software Issues

ACTION Update DTV software to latest version.

Sharp Electronics (UK) Limited

Reference – LV-219
Revision - 1

White – Carry out as required
Yellow – Carry out as required and whenever the unit comes in for service
Red – Carry out on all units